

TEXAS TRANSPORTATION COMMISSION

Lubbock County

MINUTE ORDER

Page 1 of 1

Lubbock District

Minute Order 115000, dated July 27, 2017, designated SL 88 on a new location from US 84 northwest of Lubbock to US 84 southeast of Lubbock, a distance of approximately 36.9 miles. Lubbock County and the Lubbock District have requested the following actions upon completion of SL 88: (1) designation of a segment of US 84 along SL 88 from the intersection of FM 2641 southeastward to the intersection of CR 9657, a distance of approximately 36.9 miles, thereby making SL 88 concurrent with US 84; and (2) redesignation of a segment of US 84 as BU 84-D from the intersection of US 84 and FM 2641 southeastward to the intersection of US 84 and CR 9657, a distance of approximately 36.0 miles.

Pursuant to Texas Transportation Code, §§201.103 and 221.001, the executive director of the Texas Department of Transportation has recommended these actions.

The Texas Transportation Commission (commission) finds that these actions will facilitate the flow of traffic, promote public safety, and maintain continuity of the state highway system and are necessary for the proper development and operation of the system.

IT IS THEREFORE ORDERED by the commission that upon completion of SL 88, a segment of US 84 is designated along SL 88 from the intersection of FM 2641 southeastward to the intersection of CR 9657, a distance of approximately 36.9 miles, thereby making SL 88 concurrent with US 84, and a segment of US 84 is redesignated as BU 84-D from the intersection of US 84 and FM 2641 southeastward to the intersection of US 84 and CR 9657, a distance of approximately 36.0 miles, as shown on Exhibit A.

Submitted and reviewed by:


Recommended by:

DocuSigned by: Peter Smith
186CA618CEFD410...
Director, Transportation Planning and Programming Division

DocuSigned by: James M Bass
A36629DA547D4BD...
Executive Director

115841 Aug 27 2020

Minute Number Date Passed



— — — — Designate Segment of US0084 on New Location, Along Proposed SL0088
— — — — Redesignate Segment of US0084 as BU0084-D

